

**Torrance Fire Department**

FDID: **19200** State: **CA** Date: **08/24/2021** Station: Incident #: **21-0009517** Exposure: **0**  
 Agency Address:

**BASIC MODULE (NFIRS-1)**

Location Type: **Street address** Census Tract:  
 Address: **19951 MARINER Avenue** City, State & Zip **TORRANCE, California 90503**  
 Incident Type: **131-Passenger vehicle fire - 131** Aid Given/Received: **None**

**Dates and Times**

Alarm: **08/24/2021 13:59** Arrival: **08/24/2021 14:06** Controlled: Last Unit Cleared: **08/24/2021 17:27**

**Shifts And Alarms**

Shift: **B** Alarms: District: **Q23**

**Special Studies**

Special Study ID	Value
------------------	-------

Actions Taken: **Extinguishment by fire service personnel - 11 (11)**

**Resources**

Apparatus			Personnel		
Suppression: <b>1</b>	EMS: <b>0</b>	Other: <b>0</b>	Suppression: <b>4</b>	EMS: <b>0</b>	Other: <b>0</b>

**Estimated Dollar Losses and Values**

Losses		Pre-Incident Value	
Property: <b>10000</b>	Contents: <b>35000</b>	Property:	Contents:

**Casualties**

Fire Service Deaths: **0** Fire Service Injuries: **0** Civilian Deaths: **0** Civilian Injuries: **0**

Property Use: **965 - Vehicle parking area - 965**

**Person / Entity Involved**

Phone Number: Business Name:  
 Full Name:  
 Address:

**Narrative**

Primary Jurisdiction: TFD; CAD Incident Number: 21-0009517; CAD Problem/Nature: FIRE VEHICLE; Call Disposition:

At 1359 hours on Tuesday August 24th, 2021, 1 vehicle was assigned to this incident. 4 personnel responded. The incident occurred at 19951 MARINER Avenue, TORRANCE.

Alarm number 0009517 has been assigned to this incident.

E-96 responded to a report of a vehicle on fire at a business. E-96 arrived on scene and was directed by the RP to the rear of Canoo Corporate office building. E-96 located the vehicle and deployed a hose line to begin extinguishing the fire. E-96 was met by another Canoo representative who stated the they had Lithion Car batteries in the vehicle and that one of the batteries had exploded causing the fire. They also stated that they were unsure of the condition of the other battery which was being transported in the vehicle. After the vehicle fire was extinguished E-96 contacted LA County Health Hazmat to respond to assist in the investigation of the exploding battery. LA County Health Hazmat arrived on scene. TFD personnel assisted in removing the batteries from the damaged vehicle and placing them into trash can filled with water under the direction of LA County Health Hazmat. After the batteries where placed into the trash can the scene was turned over to LA County Health Hazmat officer to complete his investigation. With no other emergencies E-96 went available.

**Remarks**

E-96 responded to a report of a vehicle on fire at a business. E-96 arrived on scene and was directed by the RP to the rear of Canoo Corporate office building. E-96 located the vehicle and deployed a hose line to begin extinguishing the fire. E-96 was met by another Canoo representative who stated the they had Lithion Car batteries in the vehicle and that one of the batteries had exploded causing the fire. They also stated that they were unsure of the condition of the other battery which was being transported in the vehicle. After the vehicle fire was extinguished E-96 contacted LA County Health Hazmat to respond to assist in the investigation of the exploding battery. LA County Health Hazmat arrived on scene. TFD personnel assisted in removing the batteries from the damaged vehicle and placing them into trash can filled with water under the direction of LA County Health Hazmat. After the batteries where placed into the trash can the scene was turned over to LA County Health Hazmat officer to complete his investigation. With no other emergencies E-96 went available.

**FIRE MODULE (NFIRS-2)**

**On-Site Materials or Products**

Material/Product ID	Material/Product Name	Storage Use
---------------------	-----------------------	-------------

**Ignition**

Area of Fire Origin: **82 - Cargo/trunk area—all vehicles**  
Heat Source: **41 - Heat, spark from friction**  
Item First Ignited: **81 - Electrical wire, cable insulation**  
Cause of Ignition: **3 - Failure of equipment or heat source**  
Factors Contributing: **Improper container or storage procedure (18)**  
Human Factors Contributing: **Unattended or unsupervised person (3)**

**Equipment Involved in Ignition**

Equipment Involved: **200 - Electrical distribution, power transfer, other**  
Power Source: **10 - Electrical, other** Portability: **1 - Portable**

**Mobile Property Involved**

Mobile Property Involved: **1 - Not involved in ignition, but burned**  
Type: **20 - Freight road transport vehicle, other** Make: **FO - Ford**

**APPARATUS OR RESOURCES / PERSONNEL MODULES (NFIRS-9/10)**

ID: **E96** Type: **11 - Engine**

Use: **1 - Suppression** Number of People: **4**  
Dispatch Time: **08/24/2021 14:00** Arrival Time: **08/24/2021 14:06** Clear Time: **08/24/2021 17:27**  
Remarks:

Personnel ID: **14336** Name: **John Judy**

Rank / Grade: **Engineer**

Personnel ID: **16601** Name: **Howell Bradley**

Rank / Grade: **Fire Fighter**

Personnel ID: **17050** Name: **Michael Berry**

Rank / Grade: **Captain**

Personnel ID: **19096** Name: **Luke Linamen**

Rank / Grade: **Fire Fighter**

**SIGNATURES / AUTHORIZATIONS**

Date/Time: Signed By: **Michael Berry**

Rank: **Captain** Assignment:

Reason: **Officer in Charge, Member making report**